Need to maintain good access to DNR boat landing

Native America artifacts found in these areas

Potential historic building (old town hall)

Potential haz-mat site (previously a gas station)

Undesirable sag curve at RR crossing

Evaluate options to widen causeway and bridge

Evaluate means of improving vertical and horizontal roadway alignments

Coordinate stormwater management with township as they are in process of addressing drainage issues along Cactus Acres Road

Columbia CTH "V"
(STH 113 to CTH "J")
Columbia County, Wisconsin

AYRES ASSOCIATES

Potential historic building

Crest vertical curve along STH 13 limiting sight distance at CTH "V" intersection

Evaluate rerouting CTH "V" along Shamrock Road to improve RR Crossing

Impacted parklands will need to be evaluated with respect to 4F requirements

Restaurants, motel, and bait shop attract large number of bicycle/ pedestrian traffic

Potential historic building (Astylistic Ulitarian Building)

Steep slope extending down to lake from edge of existing roadway

Utilities along roadway

Evaluate improving horizontal curve at intersection with Ryan Road

Evaluate means of improving vertical crest curve

Speeding and potential crash problem at intersection with CTH "J" (four reported crashes in last four years)